

March 18, 2010

*Via Federal Express*

Division of Remediation Support  
New Jersey Department of Environmental Protection  
Office of Community Relations  
401 East State Street, 6<sup>th</sup> Floor  
P.O. Box 413  
Trenton, New Jersey 08625



**Re: Public Notification Information  
Budd Lake General Store  
207 Route 46  
Mt. Olive, Morris County, New Jersey  
NJDEP Case No. 09-12-25-2141-36  
PI # 514280**

In accordance with the Public Notification requirements of N.J.A.C. 7:26E-1.4 and the updated NJDEP website guidance dated January 20, 2010, attached is the following documentation for the above-referenced site. Copies are provided in both hard copy and electronic formats:

- Photographs of Notification sign, as posted, and
- Site Information Form.

Should you have any questions regarding the enclosed materials, please give me or Ms. Alison Kokorsky a call at 908-218-0066, extensions 119 respectively. I can also be reached via e-mail at [akokorsky@jmsorge.com](mailto:akokorsky@jmsorge.com).

Yours truly,



Alison Kokorsky  
Project Manager

Enclosure

cc: Mt. Olive Township Clerk - Lisa Lashway, RMC - Paper and electronic copy  
Frank Wilpert Sr., Mt. Olive Health Department - Health Officer - Paper and electronic copy  
Mr. James Deacon - Morris County Office of Health Management - Paper and electronic copy  
Mr. Sumant Desai - Sumira, Inc. - Paper copy  
Mr. Joseph M. Sorge - JM Sorge, Inc. - Paper and electronic copy  
Mr. Atul Shah, PE - ANS Consultants - Electronic copy

## Site Information Form

<b>Site Information:</b>	Budd Lake General Store 207 Route 46 Block 4400; Lot 52 Mt. Olive, Morris County, New Jersey 07828 NJDEP Case No. 09-12-25-2141-36 PI # 514280
<b>Site Status:</b>	Contamination has been identified in the soil at the site and the surface water adjacent to the site. Receptor evaluations, as well as, soil and surface water delineation are in progress. A groundwater investigation will be completed once a well permit is obtained.
<b>Contamination Description:</b>	Elevated levels of petroleum hydrocarbons and Base Neutral compounds are present in the site soil. An emergency response action was completed by the County Haz Mat to address impacts to adjacent surface water.
<b>Remedial Actions:</b>	A limited volume of surficial soils were excavated during the SI sampling to effect primary source removal. Absorbent materials have been deployed in the adjacent stream. Further remedial investigation activities are anticipated to begin on or about March 25, 2010.
<b>Site Contacts:</b>	Mr. Sumant Desai Sumira, Inc. 708 Route 46 Kenvil, New Jersey 07847 908-723-1001  Environmental Consultant - LSRP Joseph M. Sorge JM Sorge, Inc. 57 Fourth Street Somerville, NJ 08876 908-218-0066  Division of Remediation Support New Jersey Department of Environmental Protection Office of Community Relations 401 East State Street, 6 <sup>th</sup> Floor P.O. Box 413 Trenton, NJ 08625 609-984-3081
<b>Further Information:</b>	Sumira, Inc. will provide a copy of the site reports to the municipality upon request.

**Environmental Investigation / Cleanup In Progress**

Site ID: PI # 514280    Date Posted: 3/5/2010

For Further Information Contact:

**Sumant Desai, Sumira, Inc.**  
**(973) 723-1001**

Alternately You May Contact:

 **JM Sorge, Inc.**  
environmental consultants  
Joseph M. Sorge, LSRP  
57 Fourth Street • Somerville, NJ 08876  
908-218-0066

